

Menu

HISTORY FILE MAP for year 2002

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

182.20:13-20:25: 10m 512bps data and 2m
1024bps realtime data lost due to DSS-63
receiver controller and telemetry processor
failure. DR M100848 refers.

